

6/11/1987

Please print or type
Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039 Expires 9-30-88

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. WAD 000812917		Manifest Document No. 109364		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address CHEMICAL PROCESSORS, INC. PIER 91, SEATTLE, WA. 98119 5501 AIRPORT WAY SO. SEATTLE, WA 98108 4. Generator's Phone (206) 284-2450						A. State Manifest Document Number			
5. Transporter 1 Company Name RESOURCE RECOVERY						6. US EPA ID Number WAD 001672812			
7. Transporter 2 Company Name						8. US EPA ID Number			
9. Designated Facility Name and Site Address <input type="checkbox"/> Chempro 734 So. Lucile St. Seattle, WA (206) 767-0350 <input type="checkbox"/> Chempro Pier 91 Seattle, WA (206) 284-2450 <input type="checkbox"/> Chempro 1701 Alexander Tacoma, WA (206) 627-7568 <input checked="" type="checkbox"/> Other CHEM SECURITY SYSTEMS						10. US EPA ID Number WAD 000812909 WAD 000812917 WAD 020257945 ORD 089452353			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers		13. Total Quantity	
a. HAZARDOUS WASTE SOLID N.O.S. ORM-E 9189 ORM 34						No. Type		14. Unit Wt/Vol	
b. 34 DM						9.25 cu yd		WTOZ	
c. 501						1981			
J. Additional Descriptions for Materials Listed Above PROFILE # E41865 OIL & TANK BOTTOM SOLIDS						K. Handling Codes for Wastes Listed Above E41865 S4 9.18 14,960			
15. Special Handling Instructions and Additional Information									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment, OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name ROBERT M. MOODY						Signature Robert M. Moody		Month Day Year 6 10 87	
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name ROGER MCATEE		Signature Roger McAtee	
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name		Signature	
19. Discrepancy Indication Space Add X004 Sec 1 OK per #00 Utawood Sec 11 a. ID #516 NA-9189 Sec 13 should read 9.25.00 Sec Attached									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.						Printed/Typed Name DARLENE DEEN		Signature Darlene Deen	
						Month Day Year 6 11 87			

USEPA RCRA



3012720



Star Route • Arlington, Oregon 97812-9709 • (503) 454-2643

July 10, 1987

CSSI

Chemical Processors, Inc.

5501 Airport Way S.

Seattle, WA 98108

RE: Discrepancy on Manifest No. 09364 ; Profile No. E41865 .

Date of Load: 6-11-87 ; CSSI Load No. 84696-01

Dear Sirs:

DISCREPANCY(S) OR PROBLEM(S) FOUND: This letter is to inform your office of the following discrepancy(s) found on a shipment of waste material to our facility.

EPA/State Waste Code(s) not in agreement with the profile.

‡ difference in quantity.

Number of containers found on truck does not agree with that listed in Section 12 or 29 of manifest.

drums are rejected and are returned to generator because

X The entire load is rejected and is returned to generator because of High Sulfides

Waste Type Discrepancy:

CSSI TOOK THE FOLLOWING ACTION REGARDING THIS PROBLEM:

X Cheryl Sayler, representative of CSSI notified
Rick Morton, the above generator's representative on
7-10-87, and the above problem was resolved by Returning load to generator

The material is being held pending resolution of the problem. If you need further information, please call

Sincerely,

Darrell Clough

COPY DISTRIBUTION: Original-Attach to Original Manifest

cc-TSDF manifest copy to Receiving Dept.

cc-Transporter 1 & 2 (if applicable) to Transporter(s)

cc-Accounting Dept.

cc-Sales Dept. - Cheryl Sayler